

VEHICLE INSPECTION REPORT

RV70DFD

Iveco Eurocargo 75E16

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date 22/10/2020

Year 2020

Mileage 88,420 Km Warranted

Fuel Type Diesel

Colour WHITE

VIN ZCFA875B702700739

Body Style Box Van

MOT Due 30/11/2025

Cab Type DAY CAB

Gearbox AUTOMATIC

Axle Combi 4x2

Rear Suspension Steel

Rear Doors Roller

Tail Lift Column

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4

Spare NSO1 NSO2 NSO3 NSO4

OSO1 OSO2 OSO3 OSO4

Features

- Cruise control
- Radio/CD
- Air conditioning
- Front electric windows
- Cloth seat trim


Photos








Condition Check



Damage Photos



1: Panel Front
Scratched
Over 25mm Not Thru Paint



2: Bumper Front
Cracked
Over 25mm



3: Door Mirror Assy osf
Broken
Replace



4: Qtr Panel nsr
Scratched
Over 25mm Not Thru Paint



5: Qtr Panel osr
Scratched
Over 25mm Not Thru Paint



6: Qtr Panel osr
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint



8: Door osf
Scratched
Over 25mm Thru Paint



9: Seat Base Cover nsf
Soiled
Heavy

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	Poor	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		