

VEHICLE INSPECTION REPORT

DG670SD

Man TGS 26.230

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 To Follow

Details

Reg. date 23/11/2017

Colour BLUE

Cab Type DAY CAB

Year 2017

VIN WMA18SZZ3JP096261

Gearbox AUTOMATIC

Mileage 180,536 Km Warranted

Body Style Curtainside

Axle Combi 6x2

Fuel Type Diesel

MOT Due 01/07/2026

Rear Suspension Air

MOFFET BRACKET, REAR-LIFT, SERVICE SCHEDULE LIST AVAILABLE

Tyres

NSF NSI1 NSI2 NSI3 NSI4

OSF OSI1 OSI2 OSI3 OSI4


Spare NSO1 NSO2 NSO3 NSO4


OSO1 OSO2 OSO3 OSO4

Features

- Park assist camera


Photos







Condition Check



Damage Photos



1: Wing of
Chipped
Multiple Chips



2: Bonnet
Cracked
Replace



3: Screen Front
Chipped
UpTo 10mm



4: Fog Lamp Surround os
Scuffed (Unpainted)
UpTo 100mm



5: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



6: Fog Lamp Surround ns
Scuffed (Unpainted)
UpTo 100mm



7: Bumper Front Moulding
Scuffed (Unpainted)
UpTo 100mm



8: Other
N/A
N/A



9: Door nsf
Chipped
Edge Chip



10: Other
N/A
N/A



11: Other
N/A
N/A



12: Bumper Rear
Rusted
Over 5mm



13: Other
N/A
N/A



14: Other
N/A
N/A



15: Door osf
Chipped
Multiple Chips



16: Door osf
Chipped
Edge Chip



17: Seat Base Cover osf
Holed
Over 3mm

Interior

Carpet Condition	Average		Upholstery Condition	Average
Seat Condition	Average		Odour	-
Engine Runs	OK		Gearbox 1st and Reverse Test	OK
Brakes	OK		Clutch Slip Test from Static	OK
Parking Brake	OK		Gearbox Static Gear Selection (engine running)	OK
			No Excessive Smoking	OK
EML light illuminated	OK		Oil warning light illuminated	OK
Airbag light illuminated	OK		DPF light illuminated	OK
ABS light illuminated	OK		Service indicator light illuminated	OK