

VEHICLE INSPECTION REPORT

DG66RZT

Man TGM 18.250

Inspection

Serious Damage? No

Vehicle

VAT Plus VAT

V5 Present

Details

Reg. date	10/11/2016	Colour	BLUE	Cab Type	DAY CAB
Year	2016	VIN	WMAN08ZZ5HY350438	Gearbox	MANUAL
Mileage	185,716 Km Warranted	Body Style	Dropside & Crane	Axle Combi	4x2
Fuel Type	Diesel	MOT Due	30/11/2025	Rear Suspension	Steel

HMF 1430 L1 REMOTE CRANE (YEAR 2016), SERVICE SCHEDULE & LAST CRANE TEST AVAILABLE

Tyres

NSF	NSI1	NSI2	NSI3	NSI4
OSF	OSI1	OSI2	OSI3	OSI4
Spare	NSO1	NSO2	NSO3	NSO4
	OSO1	OSO2	OSO3	OSO4

Features

- Cruise control
- Digital radio
- Radio/CD
- Front electric windows
- Cloth seat trim


Photos







Condition Check



Damage Photos



1: Bonnet
Chipped
Multiple Chips



2: Bumper Front Moulding
Scuffed (Unpainted)
Over 100mm



3: Door nsf
Scratched
Over 25mm Thru Paint



4: Wing nsf
Scratched
Over 25mm Thru Paint



5: Qtr Panel Moulding os
Broken
Replace



6: Wing osf
Scratched
Over 25mm Thru Paint



7: Door osf
Scratched
Over 25mm Thru Paint

Interior

Carpet Condition	OK	Upholstery Condition	OK
Seat Condition	OK	Odour	-
Engine Runs	OK	No Excessive Smoking	OK
EML light illuminated	OK	DPF light illuminated	OK
ABS light illuminated	OK		